# STATE LOAD DESPATCH CENTER

# AGENDA FOR 60<sup>th</sup> MEETING Of

## **State Level Co-ordination Forum**

**Date: 24/01/2020** Venue:SLDC

ITEM No:1.CONFIRMATION OF THE MINUTES OF 59<sup>th</sup>SLCF MEETING HELD ON 23.09.2019.

The minutes were circulated vide memo no: **SLDC/How/109/2019-20/924** dated 27/11/2019 and the same was also published in the website (<u>www.wbsldc.in</u>).

---- Members may please discuss.

## ITEM No: 2.REVIEW OF STATE GRID PERFORMANCE:

Power point presentation on grid performance for the month of September-19, October-19, November 19 and December-19.

---- Members may please note.

#### ITEM No. 3. IMPORTANT GRID INCIDENTS:

- 1. On 05.11.19 at 06.52 hrs total power failure occurred at Arambag 400 KV Sub-station.
  - --- WBSETCL representatives may please deliberate.
- 2. Bus fault at Liluah 132 KV sub stn at 02.36 hrs on 27.11.2019 causing power interruption in CESC system and Liluah sub stn. Subsequently CESC system got islanded.
  - --- CESC and WBSETCL representatives may please deliberate.
- 3. On 29.11.19 at 11.40 hrs total power failure occurred at 132 KV AB -Zone Sub-stn, Durgapur.
  - --- WBSETCL representatives may please deliberate.
- 4. 220 KV Sadaipur ckt#2 B phase CT burst out at Gokarna 220 KV sub-stn subsequent tripping of all 220 KV feeders on 06.12.19 at 11.00 hrs.
  - --- WBSETCL representatives may please deliberate.

#### ITEM No: 4. OPERATIONAL PLANNING:

(a) ANTICIPATED POWER SUPPLY POSITION FOR THE MONTH OF FEBRUARY 2020, MARCH 2020 AND APRIL 2020.

[All concerned are requested to furnish anticipated demand and generation forecast for these months to SLDC]

(b) SETTLEMENT OF SHUT DOWN PROPOSALS FOR THE MONTH OF FEBRUARY 2020, MARCH 2020 AND APRIL 2020. i.r.o GENERATING UNITS, TRANSMISSION LINES AND OTHER EQUIPMENTS.

[All concerned are requested to furnish their shut down proposals for these months to SLDC]

#### ITEM No: 5. AGENDA NOTE PUT UP BY SLCF MEMBERS FOR DISCUSSION:

## 5.1. Agenda note put up by BkTPP

- A. It has been observed in the past that during backdown time SG was reduced less than 10 MW in first block of ramp down(for both Stage-1 and Stage-2 units) and in the second block, SG was reduced 90 MW for stage 1 and 60 MW for stage-2. This type of SG is impossible to maintain. So it is requested that in the first block of ramp down during backdown, SG value to be reduced to atleast 50 % of maximum value of ramp down system for 1<sup>st</sup> block.
  - **B**. Auto refresh system of SLDC website is still not available.
- C. WBSEDCL did not agree with the proposal that DC for unit back down should be credited during ramp up process, that is from unit synchronization to achieving full load in the 59<sup>th</sup> SLCF meeting but representative of WBSEDCL did not mention any specific reason for that. So, we once again demand that the capacity charge during ramp up process (after withdrawal of Unit back down) to be credited from unit synchronization to achieving at least minimum technical load.
  - **D.** Carrier signal failure (PLCC) of both channels, of 400kV Bakreswar- Jeerat Line feeder, is coming frequently on/from 13/11/2019 evening. It is persisting for one/two minute and getting reset automatically. After 05-06(Five) minutes later, the signal failure of both channels is coming again. This is mostly happening in evening time after 17:00 hrs.

Testing Dep't of Bktpp has checked the signal strength at PLCC panel at BKTPP end [Receive Signal at co-axial point] repetitively & found (-16 DB) instead of min value of (-14 DB), each time. In this condition,the trouble may please be resolved for successful A/R [During zone#1 & zone#2 faults of both end ] as early as possible. If required , end to end test can also be conducted. Since this PLCC system is under 05(Five) years warranty period & controlling authority is WBSETCL Communication, Abhiskhan, so, you are requested to depute Service Engineer of M/S CGL as early as possible.

You were mailed regarding this on 27/11/2019 Prior to that Mr. Tipuram Das visited the Bakreswar Thermal Power Plant on 11.10.2019 and found same problem persisting After replacing the processor module (PTPL-4) now link/system made stable But again the trouble is occurring.

Please resolve the issue as early as possible.

# 5.2. Agenda note put up by KTPS

**A.** As per minutes of 54<sup>th</sup> SLCF meeting (Point no 6.2) held on 18.04.2018, the procurement of new APEX meter is to be taken care of by CTD,WBSETCL. But till date the replacement of meter is not initiated.

ITEM No: 6. Date and venue of next SLCF (i.e. 61<sup>th</sup>) Meeting.

**ITEM No: 7. MISCELLANEOUS:** 

### Copy for information please:-

- 1. The Secretary, WBERC,FD-415A, PouraBhavan, 3<sup>rd</sup> Floor, Bidhannagar, Kolkata-700 106
- 2. PS to Managing Director, WBSETCL, Vidyut Bhavan, Kolkata-91.
- 3. PS to Managing Director, DPL, Kolkata -107.
- 4. PS to Director (Operations), WBSETCL, Vidyut Bhavan, Kolkata-91.
- 5. PS to Director (RT), WBSEDCL, Vidyut Bhavan, Kolkata-91.
- 6. PS to Executive Director (OS), WBPDCL, Salt Lake City, Kolkata-700 098.
- 7. C.E, SLDC, WBSETCL, Howrah-09.
- 8. C.E, Transmission-I, WBSETCL, Vidyut Bhavan, Kol-91.
- 9. C.E, Transmission-II, WBSETCL, Vidyut Bhavan, Kol-91.
- 10. C.E, CTD, WBSETCL, AbhiksanBhavan, Kol-91.
- 11. C.E, Communication, WBSETCL, AbhiksanBhavan, Kol-91.
- 12. Chief Engineer, CLD, DVC, Howrah.
- 13. C.E.(PTP) WBSEDCL, Vidyut Bhavan, Kolkata-91.
- 14. G.M, (SO) CESC Ltd., Statesman House, Kol- 01.
- 15. G.M. BTPS, WBPDCL.
- 16. G.M. STPS, WBPDCL.
- 17. G.M. KTPP, WBPDCL.
- 18. G.M. BKTPP, WBPDCL.
- 19. G.M. SGTPP, WBPDCL.
- 20. Sri I. B. Chakraborty, Vice-President, Engineering & Projects, IPCL
- 21. Addl. Chief Engineer, SLDC, WBSETCL, Howrah-09.
- 22. Addl. Chief Engineer, Communication (Howrah), WBSETCL, Howrah-09.
- 23. Addl. Chief Engineer, ALDC, WBSEDCL.
- 24. Sri P. Gupta, DGM, WBPDCL.
- 25. Sri A. Sen Gupta, DGM, System Control Department, CESC Ltd, CESC House, Kol- 01.
- 26. Sri S. K. Sarkar, G.S.(T&D, Load Management), DPSC Ltd.
- 27. Sri R. Biswas, Sr. Manager, ALDC, DPL.
- 28. Sri GoutamBose, Sr. Manager & HOD (Operation), KTPP WBPDCL,
- 29. Sri IndrajitBanerjee, Manager (Operation), KTPP WBPDCL.
- 30. Sri D. Chanda, Sr. Manager (PS), BKTPP, WBPDCL.
- 31. Mr. Joynal Abedin, Sr. Manager (E.O.), BKTPP, WBPDCL.
- 32. Sri K. Banerjee, Manager, System Control Department, CESC Ltd, CESC House, Kol- 01.
- 33. Sri A.Biswas, Manager(PS), BKTPP, WBPDCL.
- 34. Sri F.Hossain, Manager (PS), SGTPP, WBPDCL.
- 35. Sri M.S.Bapari, Manager (PS), SGTPP, WBPDCL.
- 36. Sri M. Mallik, Sr. Manager, (System Operation Electrical), BTPS, WBPDCL.
- 37. Sri S. Maiti, Sr. Manager (O), STPS, WBPDCL.